

TABLE 1

MANAGEMENT/ MAINTENANCE - Incidence Sheet, Asbestos Register

Site Address: Merton Park Primary School, Church Lane, London, SW19 3HQ

Date: 04/08/2010

Key:

Presumed / Strongly Presumed / No Access

N.A.V.D. = No Asbestos Visually Detected

Material scores above 10 have a high potential to release fibres

LOCATION: Building No., Floor Level and Room Number	POSITION / DESCRIPTION	Material Type	Level Of I.D.	Asbestos Type	Extent m ² Quantity	Photo No.	Access	Surface Treat.	Condition	Fixing	Material Assessment, Actions
External	Site					258					
External			N A V D								
Ground Floor											
0/001 Office			N A V D								
0/003 Ex-boiler room	Flash pads to electrical switchgear	Textile	Presumed	Chrysotile (White)	X6	260	Low	None	Low	Clipped	5 - Manage
0/004 Ladies WC			N A V D								
0/005 Office			N A V D								
0/005A Secondary Office			N A V D								
0/006 Circ			N A V D								
0/007 WC			N A V D								
0/008 Female WC			N A V D								
0/009 Store			N A V D								
0/009 & 0/036 Loft above 09 & 36			N A V D								
0/009A Office			N A V D								
0/010 Boys WC			N A V D								
0/011 Library			N A V D								
0/011A Store			N A V D								
0/011B Music room			N A V D								

TABLE 1

MANAGEMENT/ MAINTENANCE - Incidence Sheet, Asbestos Register

Site Address: Merton Park Primary School, Church Lane, London, SW19 3HQ

Date: 04/08/2010

Key:

Presumed / Strongly Presumed / No Access

N.A.V.D. = No Asbestos Visually Detected

Material scores above 10 have a high potential to release fibres

LOCATION: Building No., Floor Level and Room Number	POSITION / DESCRIPTION	Material Type	Level Of ID.	Asbestos Type	Extent m ² Quantity	Photo No.	Access	Surface Treat.	Condition	Fixing	Material Assessment, Actions
0/012 Kitchen			N A V D								
0/013 Store			N A V D								
Main loft			N A V D								
0/014 Boiler room			N A V D								
0/016 Staff room			N A V D								
0/017 Multi purpose			N A V D								
0/018 WC			N A V D								
GF20 Disabled WC			N A V D								
0/021 Reception			N A V D								
0/022 Store			N A V D								
0/024 Cloakroom			N A V D								
0/025 Classroom			N A V D								
0/026 ICT room			N A V D								
0/027A Store			N A V D								
0/027 Classroom			N A V D								
0/028 Store			N A V D								
0/029 Store			N A V D								
0/030 Multi purpose	Electrical switch gear	Textile	Presumed	Chrysotile (White)	X6	270	Low	Unsealed	Good	Clipped	5 - Manage
0/031 Store			N A V D								

TABLE 1

MANAGEMENT/ MAINTENANCE - Incidence Sheet, Asbestos Register

Site Address: Merton Park Primary School, Church Lane, London, SW19 3HQ

Date: 04/08/2010

Key:

Presumed / Strongly Presumed / No Access

N.A.V.D. = No Asbestos Visually Detected

Material scores above 10 have a high potential to release fibres

LOCATION: Building No., Floor Level and Room Number	POSITION / DESCRIPTION	Material Type	Level Of I.D.	Asbestos Type	Extent m ² Quantity	Photo No.	Access	Surface Treat.	Condition	Fixing	Material Assessment, Actions
0/032 Classroom			N.A.V.D								
0/033 Classroom			N.A.V.D								
0/033 Classroom			N.A.V.D								
0/034 Classroom			N.A.V.D								
0/035 Classroom			N.A.V.D								
0/035 Classroom			N.A.V.D								
0/036 Clrc			N.A.V.D								
0/037 Clrc			N.A.V.D								
0/038 Clrc			N.A.V.D								
0/039 Clrc			N.A.V.D								
0/040 Nursery			N.A.V.D								
0/041 Play room			N.A.V.D								
0/042 Boys WC			N.A.V.D								
0/043 Office			N.A.V.D								

MERTON PARK PRIMARY SCHOOL

**Church Lane
Merton Park
London
SW19 3HQ
Tel: 0208 542 7128**

Q:/premises/asbestos condition monitoring