

SITE	BUILDING	LOCATION	MAKE AND MODEL	HEATING/COOLING	SERVICE SCHEDULE
BOC	ACADEMIC	STUDENT UNION SHOP	Daikin FXQ63AVEB Indoor A/C Unit	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	ACADEMIC	STUDENT UNION SHOP	Daikin FXQ63AVEB Indoor A/C Unit	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	ACADEMIC	STUDENT UNION SHOP OFFICE	Daikin FXAQ25PAV1 Indoor A/C Unit	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	ACADEMIC	LOANS, MEDIA STORE	Heat Recovery Unit		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	ACADEMIC	SECURITY/CARETAKERS OFFICE	Daikin Indoor A/C Unit	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	ACADEMIC	GROUND FLOOR	Ventilation Control Panel	n/a	n/a
BOC	ACADEMIC	GROUND FLOOR	Ventilation Control Panel	n/a	n/a
BOC	ACADEMIC	I.T. ROOM	Daikin Indoor A/C Unit		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	ACADEMIC	I.T. ROOM	Daikin Indoor A/C Unit		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	ACADEMIC	2ND FLOOR	Ventilation Control Panel	n/a	n/a
BOC	ACADEMIC	ROOF	Flaktwood AHU 1		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	ACADEMIC	ROOF	DX Control Box 2	n/a	n/a
BOC	ACADEMIC	ROOF	DX Control Box 1	n/a	n/a
BOC	ACADEMIC	ROOF	Daikin RQ100AV7IB AHU DX 01	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	ACADEMIC	ROOF	Daikin RQ100AV7IB AHU DX 02	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	ACADEMIC	ROOF	Outside Unit Daikin REYQ2T7YIB VRV	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	HEALTHONE	GROUND FLOOR WARD 1	AHU 01 Flakt Ceiling Suspended vQ Stream (Lge)		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	HEALTHONE	GROUND FLOOR WARD 2	AHU 03 Flakt Ceiling Suspended vQ Stream (Lge)		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	HEALTHONE	GROUND FLOOR O/S SIMULATION CENTRE	AHU 02 Flakt Ceiling Suspended vQ Stream Compact Units		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	HEALTHONE	GROUND FLOOR CLASSROOM	AHU 04 Flakt Ceiling Suspended vQ Stream Compact Units		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	HEALTHONE	1ST FLOOR	AHU Flakt Ceiling Suspended vQ Stream Compact		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	HEALTHONE	1ST FLOOR	AHU Flakt Ceiling Suspended vQ Stream Compact		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	HEALTHONE	1ST FLOOR	AHU Flakt Ceiling Suspended vQ Stream Compact		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	HEALTHONE	1ST FLOOR	AHU Flakt Ceiling Suspended vQ Stream (Lge)		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	HEALTHONE	1ST FLOOR	AHU Flakt Ceiling Suspended vQ Stream (Lge)		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	HEALTHONE	1ST FLOOR	AHU Flakt Ceiling Suspended vQ Stream (Lge)		Service and filter change/clean unit twice per year, disinfect coils once per year

BOC	DANCE STUDIOS 1 & 2		High level extract fans - Ziew - Abegg 101190-97057940		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	DANCE STUDIOS 1 & 2		Controls: Fan speed controllers AM/SP 5025C - Roof Units Group	n/a	n/a
BOC	DINING HALL		Thermoscreen klv-12 ceiling mounted	Heating	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	DINING HALL		Thermoscreen klv-12 ceiling mounted	Heating	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	DINING HALL		Thermoscreen klv-12 ceiling mounted	Heating	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	DINING HALL		Thermoscreen klv-12 ceiling mounted	Heating	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	DINING HALL		Thermoscreen klv-12 ceiling mounted	Heating	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	DINING HALL		Thermoscreen klv-12 ceiling mounted	Heating	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	DINING HALL		Thermoscreen klv-12 ceiling mounted	Heating	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	HOLTS	1st Floor Marketing, Recruitment, Admin	Daikin Indoor FTXS60FV1B	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	HOLTS	1st Floor Marketing, Recruitment, Admin	Daikin Indoor FTXS60FV1B	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	HOLTS	Roof	Daikin Outdoor RXS60F2VIB	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	HOLTS	Roof	Daikin Outdoor RXS60F2VIB	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Loft Void	Ecovent Crossflow Heat Recovery unit. Supply Fans: EVX244-1/FP-W/DS/LT/G4/CPSC	Extract &	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Costa/Entrance Lobby	Mitsubishi PLFY-P32VBH-E	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Costa	Mitsubishi PLFYP40VBME	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Costa	Mitsubishi PLFYP40VBME	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Costa	Mitsubishi PLFYP40VBME	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Costa	Mitsubishi PLFYP40VBME	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Grd Flr Edit Suite 1	Mitsubishi Electric PKFY-P15VBM-E	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Grd Flr Edit Suite 2	Mitsubishi Electric PKFY-P15VBM-E	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Grd Flr Edit Suite 3	Mitsubishi Electric PKFY-P15VBM-E	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Grd Flr Edit Suite 4	Mitsubishi Electric PKFY-P15VBM-E	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Grd Flr Edit Suite 5	Mitsubishi Electric PKFY-P15VBM-E	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Grd Flr Edit Suite 6	Mitsubishi Electric PKFY-P15VBM-E	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Grd Flr Edit Suite 7	Mitsubishi Electric PKFY-P15VBM-E	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year

BOC	LRC	Grd Flr Creative Suite Open Area	Mitsubishi Electric PKFY-P15VBM-E	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	CSU (location to be checked)	Mitsubishi Electric PKFY-P15VBM-E		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Outside Career Centre	Mitsubishi Electric PLFYP32VBME	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Grd Flr Head SIZ Office C13-0-02c	Mitsubishi Electric PKFY-P15VBM-E	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Interview Room	Mitsubishi Electric PKFY-P15VBM-E	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Grd Flr SIZ Office	Mitsubishi Electric PKFY-P15VBM-E	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Group Study (old Print Shop)	Mitsubishi Indoor A/C Unit PLASP71BA	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Grd Flr Reception	Mitsubishi Electric PKFY-P15VBM-E	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Grd Flr Lift motor room	Indoor A/C Unit Mitsubishi SRK25ZMS	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Library Office	Mitsubishi Indoor A/C Unit PLFYP80VBME	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	2nd Flr Special Collections	Mitsubishi Indoor A/C Unit PLARP71BA	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	2nd Flr Training Room	Mitsubishi Indoor A/C Unit PLARP71BA	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Rear of Plant room	Mitsubishi Electric Multi VRV Outdoor Unit, PURYP450YJMA	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Rear of plant room	Mitsubishi Electric Condenser Outdoor Unit, SUZSA71VA	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Rear of Plant room	Mitsubishi Heavy Industries Condenser Outdoor Unit, SRC25ZMS	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Roof	Mitsubishi Outside A/C Unit SUZKA71VA4	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Roof	Mitsubishi Outside A/C Unit SUZKA71VA4	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Plant Room (location to be checked)	JS Humidifiers HE6-85-120-120 & Control Panel		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Plant Room	Ciat Air Handling Unit GI 150 Cell Type F2 Bag Type HPR1 Supply Fan 2.2 kw motors 415 volt 3 phase 50Hz. Backward Curved. Extract Fan 2.2 kw motors 415 volt 3 phase 50Hz. Backward curved	Heating	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	LRC	Plant Room (location to be checked)	IMI Air Conditioning Unit		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	MITRE LECTURE THEATRE	ROOF	Roof mounted AHU & Package Chiller (DX Coil) VES Andover Ltd Max Ecovent PM/WP	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	MITRE LECTURE THEATRE	ROOF	VES RZQ200C7YIB	Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	MITRE LECTURE THEATRE	ROOF	VES RZQ200C7YIB	Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	MUSIC	ROOF	Flaktwood/daikin	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year

BOC	MUSIC	ROOF	Flaktwood/daikin	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	SHOWROOM		STA (Sistemi Trattamento Aria) UTA 115 DAA 26, Serial DS03105 Extract Fan: 3ph - 7.5 kw Fan Type NPE 560 Rpm 1445. Supply Fan 3ph - 4 kw Fan Type 560 RPM 1430 Controls: Trend IQ220		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	STUDENT UNION	FUNCTION ROOM AHU1	ECE UK LTD Filters: Panel (Supply) EU3, Bag (Supply) EU8, Panel (extract) EU3. Extract Fan: Motors 415 volt 3 phase 50Hz. Centrifugal. Supply Fan: Motors 415 volt 3 phase 50Hz. Centrifugal. Heating Section: Duty 47.28kw (LTHW) Frost Coil: Duty 23.64lw (LTHW) Cooling Section: Duty 23.9kw DX R407c Compressor: Airedale type CUS 3.5 no off 2 cooling capacity 11.91kw		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	STUDENT UNION	BAR AHU2	ECE UK LTD Filters: Panel (Supply) EU3, Bag (Supply) EU8, Panel (extract) EU3. Extract Fan: Motors 415 volt 3 phase 50Hz. Centrifugal. Supply Fan: Motors 415 volt 3 phase 50Hz. Centrifugal. Heating Section: Duty 47.28kw (LTHW) Frost Coil: Duty 23.64lw (LTHW) Cooling Section: Duty 23.9kw DX R407c Compressor: Airedale type CUS 3.5 no off 2 cooling capacity 11.91kw		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	STUDENT UNION	MEETING ROOM	Vent Axia air tract inline centrifugal fan unit (ACG 125-12) Filters: EU3 Heater Battery: 1.5kw	n/a	n/a
BOC	STUDENT UNION	OFFICE	Vent Axia air tract inline centrifugal fan unit (ACG 315-12) Filters: EU3 Heater Battery 1.5kw	n/a	n/a
BOC	STUDENT UNION	BAR	Vent Axia air tract inline centrifugal fan unit (ACG 125-12) Filters: EU3 Heater Battery: 1.5kw	n/a	n/a
BOC	STUDENT UNION	GROUND FLOOR TOILET	NuAire twin fan unit Ecosmart EST4		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	STUDENT UNION	FIRST FLOOR TOILET	Nuaire twin duct mounted fan unit Opus 030 2m		Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	TUDOR HALE	BIOMECHANICS LAB UNIT 1	Daikin FXFQ125AVEB	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	TUDOR HALE	BIOMECHANICS LAB UNIT 2	Daikin FXFQ125AVEB	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	TUDOR HALE	BIOMECHANICS LAB UNIT 3	Daikin FXFQ125AVEB	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	TUDOR HALE	EXERCISE PHYSIOLOGY LAB 2 UNIT 1	Daikin FXFQ80AVEB	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	TUDOR HALE	EXERCISE PHYSIOLOGY LAB 2 UNIT 2	Daikin FXFQ80AVEB	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	TUDOR HALE	SPORTS THERAPY TEACHING RM UNIT 1	Daikin FXFQ80AVEB	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	TUDOR HALE	SPORTS THERAPY TEACHING RM UNIT 2	Daikin FXFQ80AVEB	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	TUDOR HALE	SPORTS THERAPY CLINIC UNIT 1	Daikin FXFQ80AVEB	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	TUDOR HALE	SPORTS THERAPY CLINIC UNIT 2	Daikin FXFQ80AVEB	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	TUDOR HALE	REHABILITATION STUDIO UNIT 1	Daikin FXAQ63PAV1	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	TUDOR HALE	REHABILITATION STUDIO UNIT 2	Daikin FXAQ63PAV1	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year

BOC	TUDOR HALE	EXERCISE PHYSIOLOGY LAB 1 UNIT 1	Daikin FXFQ100AVEB	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	TUDOR HALE	EXERCISE PHSYIOLOGY LAB 1 UNIT 2	Daikin FXFQ100AVEB	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	TUDOR HALE	EXERCISE PHYSIOLOGY LAB 3 UNIT 1	Daikin FXFQ100AVEB	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	TUDOR HALE	EXERCISE PHYSIOLOGY LAB 3 UNIT 2	Daikin FXFQ100AVEB	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	TUDOR HALE	REAR OF TUDOR HALE - SPORTS HALL	Daikin REMQ12P8Y1B	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	TUDOR HALE	REAR OF TUDOR HALE - SPORTS HALL	Daikin REMQ12P8Y1B	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	TUDOR HALE	REAR OF TUDOR HALE - SPORTS HALL	Daikin REMQ12P8Y1B	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	UNIVERSITY HOUSE	BLACK & WHITE & D CORRIDOR O/S E123	LG 4-Way Cassette, Unit No.1 LTD2860RJ	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	UNIVERSITY HOUSE	BLACK & WHITE & D CORRIDOR O/S E123	LG 4-Way Cassette, Unit No.2 LTD2860RJ	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	UNIVERSITY HOUSE	BLACK & WHITE & D CORRIDOR POST ROOM	Mitsubishi 4-Way Cassette PLFRP71BA	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	UNIVERSITY HOUSE	SCIENCE BLOCK & H CORRIDOR E125B	Mitsubishi Lossnay, LGH35RX4E	Heat Recovery	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	UNIVERSITY HOUSE	SCIENCE BLOCK & H CORRIDOR G132	Mitsubishi Mr Slim, PLH6AKS	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	UNIVERSITY HOUSE	SCIENCE BLOCK & H CORRIDOR G131	Toshiba 4-Way Cassette, RAV462UHPE	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	UNIVERSITY HOUSE	SCIENCE BLOCK & H CORRIDOR O/S G131	Toshiba	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	UNIVERSITY HOUSE	SCIENCE BLOCK & H CORRIDOR H137	Daikin, FHQ100BVV1B	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	UNIVERSITY HOUSE	SCIENCE BLOCK & H CORRIDOR H137	Daikin, FHQ100BVV1B	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	UNIVERSITY HOUSE	SCIENCE BLOCK & H CORRIDOR CONSULTANCY ROOM	Daikin, FFQ25C2VEN	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	UNIVERSITY HOUSE	SCIENCE BLOCK & H CORRIDOR SPRU LAB	Daikin FCQ35C8VEB	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	UNIVERSITY HOUSE	External	Mitsubishi POHZRP1HA274	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	UNIVERSITY HOUSE	External	LG LTD2860RJ	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	UNIVERSITY HOUSE	External	LG LTD2860RJ	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	UNIVERSITY HOUSE	Roof	Daikin RXS25L3V1B	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	UNIVERSITY HOUSE	Roof	Daikin RZQS100B7V1B	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	UNIVERSITY HOUSE	External - Courtyard	Mitsubishi	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
BOC	UNIVERSITY HOUSE	Roof	Daikin RXS35G2V1B9	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year

BOC	UNIVERSITY HOUSE	Roof	Daikin RZQS100D7V1B	Heating/Cooling	Service and filter change/clean unit twice per year, disinfect coils once per year
-----	------------------	------	---------------------	-----------------	--