

This is a published notice on the Find a Tender service: <https://www.find-tender.service.gov.uk/Notice/000205-2024>

Not applicable

Structural Engineering services

Britten Pears Arts

F14: Notice for changes or additional information

Notice identifier: 2024/S 000-000205

Procurement identifier (OCID): ocds-h6vhtk-0429fe

Published 4 January 2024, 12:02pm

Section I: Contracting authority/entity

I.1) Name and addresses

Britten Pears Arts

Snape Maltings Concert Hall

Saxmundham

IP17 1SP

Contact

Ken Baines

Email

kbaines@brittenpearsarts.org

Telephone

+44 7970161832

Country

United Kingdom

Region code

UKH14 - Suffolk

Companies House

00980281

Internet address(es)

Main address

www.brittenpearsarts.org

Section II: Object

II.1) Scope of the procurement

II.1.1) Title

Structural Engineering services

II.1.2) Main CPV code

- 71312000 - Structural engineering consultancy services

II.1.3) Type of contract

Services

II.1.4) Short description

Structural Engineering Services RIBA Stages 0 - 7 across multiple workstreams as described in the Invitation to Tender

Section VI. Complementary information

VI.6) Original notice reference

Notice number: [2023/S 000-037983](#)

Section VII. Changes

VII.1) Information to be changed or added

VII.2) Other additional information

Tender Clarification Number 1 following tender query.

Q1. We note that at Section 3 / Questionnaire (Item 8.1a) you are seeking a commitment to Professional Indemnity Insurance to a level of £10,000,000 which does seem high for the scope of structural work involved. Was there a specific area of the programme that you felt warranted this level of cover? We note that this is a pass/fail section of the Tender so would not wish to jeopardise our bid by not committing but we are looking to understand where this level of cover would be required.

A1. The works under workstream CH1 include the need for additional structural support to the Concert Hall roof. The works under under workstream BP1 include removal of walls which may be load bearing and additional structural support to the studio roof. It was considered that £5M would not be adequate cover as it does not just relate to project construction value and the level of £10M set provided the cover necessary and therefore adjustment to a lower level is not acceptable.