

This is a published notice on the Find a Tender service: <https://www.find-tender.service.gov.uk/Notice/007584-2022>

Contract

## **Replacement control system for Hauzer TechCoating PVD Unit**

Sheffield Hallam University

F03: Contract award notice

Notice identifier: 2022/S 000-007584

Procurement identifier (OCID): ocds-h6vhtk-03243a

Published 21 March 2022, 1:54pm

### **Section I: Contracting authority**

#### **I.1) Name and addresses**

Sheffield Hallam University

City Campus, Howard Street

SHEFFIELD

S11WB

#### **Contact**

Procurement Team

#### **Email**

[strategicprocurement@shu.ac.uk](mailto:strategicprocurement@shu.ac.uk)

#### **Telephone**

+44 1142253431

#### **Country**

United Kingdom

**NUTS code**

UKE32 - Sheffield

**Internet address(es)**

Main address

<https://www.shu.ac.uk/>

**I.4) Type of the contracting authority**

Body governed by public law

**I.5) Main activity**

Education

---

## **Section II: Object**

### **II.1) Scope of the procurement**

#### **II.1.1) Title**

Replacement control system for Hauzer TechCoating PVD Unit

Reference number

CW204-LW

#### **II.1.2) Main CPV code**

- 51430000 - Installation services of laboratory equipment

#### **II.1.3) Type of contract**

Services

#### **II.1.4) Short description**

There is no other option to keep the coating unit running and bring it up to the most recent safety standards. Replacing the control system for this unit would be a fraction of the cost of an entire new unit. The cost of a new unit would be over £1.2M and would not include the bespoke modifications that the current system has. Major components of the unit have already been replaced e.g. pumping units at a cost of £139k, which were replaced in 2017.

Only the original equipment manufacturer is capable of replacing the control system for the this highly complex industrial machine. SHU tendered for replacement pumps for the machine in 2016/17 (1617-05-ACES-JM) and only Hauzer returned a submission. It would have been significantly easier to a third party to reverse-engineer the pump requirements than it would for a company to reverse engineer the control system. An analogy would be that replacing the pumps is like a lung transplant, replacing the control system is like a brain transplant. The first is very difficult, the second impossible.

#### **II.1.6) Information about lots**

This contract is divided into lots: No

#### **II.1.7) Total value of the procurement (excluding VAT)**

Value excluding VAT: £200,000

## **II.2) Description**

### **II.2.3) Place of performance**

NUTS codes

- UKE32 - Sheffield

### **II.2.4) Description of the procurement**

There is no other option to keep the coating unit running and bring it up to the most recent safety standards. Replacing the control system for this unit would be a fraction of the cost of an entire new unit. The cost of a new unit would be over £1.2M and would not include the bespoke modifications that the current system has. Major components of the unit have already been replaced e.g. pumping units at a cost of £139k, which were replaced in 2017.

Only the original equipment manufacturer is capable of replacing the control system for the this highly complex industrial machine. SHU tendered for replacement pumps for the machine in 2016/17 (1617-05-ACES-JM) and only Hauzer returned a submission. It would have been significantly easier to a third party to reverse-engineer the pump requirements than it would for a company to reverse engineer the control system. An analogy would be that replacing the pumps is like a lung transplant, replacing the control system is like a brain transplant. The first is very difficult, the second impossible.

### **II.2.5) Award criteria**

Price

### **II.2.11) Information about options**

Options: No

---

## Section IV. Procedure

### IV.1) Description

#### IV.1.1) Type of procedure

Award of a contract without prior publication of a call for competition in the cases listed below

- The procurement falls outside the scope of application of the regulations

Explanation:

COMPETITION WAIVER - There is no other option to keep the coating unit running and bring it up to the most recent safety standards. Replacing the control system for this unit would be a fraction of the cost of an entire new unit. The cost of a new unit would be over £1.2M and would not include the bespoke modifications that the current system has. Major components of the unit have already been replaced e.g. pumping units at a cost of £139k, which were replaced in 2017.

Only the original equipment manufacturer is capable of replacing the control system for the this highly complex industrial machine. SHU tendered for replacement pumps for the machine in 2016/17 (1617-05-ACES-JM) and only Hauzer returned a submission. It would have been significantly easier to a third party to reverse-engineer the pump requirements than it would for a company to reverse engineer the control system. An analogy would be that replacing the pumps is like a lung transplant, replacing the control system is like a brain transplant. The first is very difficult, the second impossible.

#### IV.1.8) Information about the Government Procurement Agreement (GPA)

The procurement is covered by the Government Procurement Agreement: No

---

## Section V. Award of contract

### Title

Replacement control system for Hauzer TechCoating PVD Unit

A contract/lot is awarded: Yes

### V.2) Award of contract

#### V.2.1) Date of conclusion of the contract

28 January 2022

**V.2.2) Information about tenders**

Number of tenders received: 1

The contract has been awarded to a group of economic operators: No

**V.2.3) Name and address of the contractor**

IHI Hauzer Techno Coating B.V.

Van Heemskerckweg 22, 5928 LL Venlo, Netherlands

5928 LL Venlo

Country

Netherlands

NUTS code

- NL - Netherlands

The contractor is an SME

No

**V.2.4) Information on value of contract/lot (excluding VAT)**

Initial estimated total value of the contract/lot: £200,000

Total value of the contract/lot: £200,000

---

## **Section VI. Complementary information**

### **VI.4) Procedures for review**

#### **VI.4.1) Review body**

Sheffield Hallam University

Sheffield

Country

United Kingdom