This is a published notice on the Find a Tender service: https://www.find-tender.service.gov.uk/Notice/010763-2023

Not applicable

Purchase and Installation of Vessel Engine Control Systems

Scottish Government

F14: Notice for changes or additional information

Notice identifier: 2023/S 000-010763

Procurement identifier (OCID): ocds-h6vhtk-038ccf

Published 14 April 2023, 11:23am

Section I: Contracting authority/entity

I.1) Name and addresses

Scottish Government

Marine Scotland, Marine Laboratory, 375 Victoria Road, Torry

Aberdeen

AB11 9DB

Contact

Bob McLeod

Email

bob.mcleod@gov.scot

Telephone

+44 1312443567

Country

United Kingdom

NUTS code

UKM - Scotland

Internet address(es)

Main address

http://www.scotland.gov.uk

Buyer's address

https://www.publiccontractsscotland.gov.uk/search/Search_AuthProfile.aspx?ID=AA1048 2

Section II: Object

II.1) Scope of the procurement

II.1.1) Title

Purchase and Installation of Vessel Engine Control Systems

Reference number

CASE/216380

II.1.2) Main CPV code

• 51100000 - Installation services of electrical and mechanical equipment

II.1.3) Type of contract

Services

II.1.4) Short description

Marine Scotland has a requirement to place a contract with an external service provider for the provision of Purchase and Installation of Vessel Engine Control Systems for two of its vessels, MRV Scotia and MPV Minna.

Section VI. Complementary information

VI.6) Original notice reference

Notice number: <u>2023/S 000-007970</u>

Section VII. Changes

VII.1) Information to be changed or added

VII.1.2) Text to be corrected in the original notice

Section number

IV.2.2

Place of text to be modified

Time limit

Instead of

Date

19 April 2023

Local time

12:00pm

Read

Date

10 May 2023

Local time

12:00pm

Section number

IV.2.7

Place of text to be modified

Instead of		
Date		
19 April 2023		
Local time		
12:00pm		

Read

Date

10 May 2023

Local time

12:00pm

VII.2) Other additional information

Conditions for opening of tenders

Delay due to lack of access to vessels due to unforeseen incident.