

This is a published notice on the Find a Tender service: <https://www.find-tender.service.gov.uk/Notice/021772-2021>

Not applicable

Energy Efficiency Contractors

Scotland Excel

F14: Notice for changes or additional information

Notice identifier: 2021/S 000-021772

Procurement identifier (OCID): ocds-h6vhtk-02dbc3

Published 2 September 2021, 4:34pm

Section I: Contracting authority/entity

I.1) Name and addresses

Scotland Excel

Renfrewshire House, Cotton Street

Paisley

PA1 1AR

Email

construction@scotland-excel.org.uk

Telephone

+44 1414888230

Country

United Kingdom

NUTS code

UKM83 - Inverclyde, East Renfrewshire and Renfrewshire

Internet address(es)

Main address

<http://www.scotland-excel.org.uk>

Buyer's address

https://www.publiccontractsscotland.gov.uk/search/Search_AuthProfile.aspx?ID=AA10383

Section II: Object

II.1) Scope of the procurement

II.1.1) Title

Energy Efficiency Contractors

Reference number

1320

II.1.2) Main CPV code

- 45300000 - Building installation work

II.1.3) Type of contract

Works

II.1.4) Short description

This notice is for a renewal framework for contractors to provide a range of energy efficiency works and services. This includes but is not limited to professional services, building fabric, heating, hot water, ventilation, renewables and energy storage measures.

Section VI. Complementary information

VI.6) Original notice reference

Notice number: [2021/S 000-021588](#)

Section VII. Changes

VII.1) Information to be changed or added

VII.2) Other additional information

Amendment to Section II.2.4) Description of the procurement within Contract Notice 645316

Section II.2.4) Description of the procurement

Stated the following :

The sublots under this lot will include; building fabric measures and finishes, cavity wall insulation, Hard to Treat (HTT) cavity wall

insulation, warm roof insulation, repair and replacement: pitched, internal wall insulation, floor insulation, doors replacement and retrofit,

windows replacement and retrofit, flat roof insulation, repair and replacement, cold roof insulation, repair and replacement: pitched.

This Should be replaced with:

The sublots under this lot will include; External wall insulation and finishes, cavity wall insulation, Hard to Treat (HTT) cavity wall

insulation, warm roof insulation, repair and replacement: pitched, internal wall insulation, floor insulation, doors replacement and retrofit,

windows replacement and retrofit, flat roof insulation, repair and replacement, cold roof insulation, repair and replacement: pitched.