This is a published notice on the Find a Tender service: <a href="https://www.find-tender.service.gov.uk/Notice/021772-2021">https://www.find-tender.service.gov.uk/Notice/021772-2021</a>

Not applicable

# **Energy Efficiency Contractors**

Scotland Excel

F14: Notice for changes or additional information

Notice identifier: 2021/S 000-021772

Procurement identifier (OCID): ocds-h6vhtk-02dbc3

Published 2 September 2021, 4:34pm

# Section I: Contracting authority/entity

## I.1) Name and addresses

Scotland Excel

Renfrewshire House, Cotton Street

Paisley

PA11AR

#### **Email**

construction@scotland-excel.org.uk

### **Telephone**

+44 1414888230

### Country

**United Kingdom** 

#### **NUTS** code

UKM83 - Inverclyde, East Renfrewshire and Renfrewshire

### Internet address(es)

Main address

http://www.scotland-excel.org.uk

Buyer's address

https://www.publiccontractsscotland.gov.uk/search/Search\_AuthProfile.aspx?ID=AA1038 3

# **Section II: Object**

## II.1) Scope of the procurement

#### II.1.1) Title

**Energy Efficiency Contractors** 

Reference number

1320

# II.1.2) Main CPV code

• 45300000 - Building installation work

# II.1.3) Type of contract

Works

## II.1.4) Short description

This notice is for a renewal framework for contractors to provide a range of energy efficiency works and services. This includes but is not limited to professional services, building fabric, heating, hot water, ventilation, renewables and energy storage measures.

# **Section VI. Complementary information**

## VI.6) Original notice reference

Notice number: <u>2021/S 000-021588</u>

# **Section VII. Changes**

## VII.1) Information to be changed or added

## VII.2) Other additional information

Amendment to Section II.2.4) Description of the procurement within Contract Notice 645316

Section II.2.4) Description of the procurement

Stated the following:

The sublots under this lot will include; building fabric measures and finishes, cavity wall insulation, Hard to Treat (HTT) cavity wall

insulation, warm roof insulation, repair and replacement:pithced, internal wall insulation, floor insulation, doors replacement and retrofit,

windows replacement and retrofit, flat rood insulation, repair and replacement, cold roof insulation, repair and replacement: pitched.

This Should be replaced with:

The sublots under this lot will include; External wall insulation and finishes, cavity wall insulation, Hard to Treat (HTT) cavity wall

insulation, warm roof insulation, repair and replacement:pitched, internal wall insulation, floor insulation, doors replacement and retrofit,

windows replacement and retrofit, flat roof insulation, repair and replacement, cold roof insulation, repair and replacement: pitched.