

This is a published notice on the Find a Tender service: <https://www.find-tender.service.gov.uk/Notice/035045-2023>

Not applicable

Lift Maintenance Services

River Clyde Homes

F14: Notice for changes or additional information

Notice identifier: 2023/S 000-035045

Procurement identifier (OCID): ocds-h6vhtk-040b45

Published 28 November 2023, 12:04pm

Section I: Contracting authority/entity

I.1) Name and addresses

River Clyde Homes

Clyde View, 22 Pottery Street

Greenock

PA15 2UZ

Email

procurement@riverclydehomes.org.uk

Telephone

+44 8000132196

Country

United Kingdom

NUTS code

UKM83 - Inverclyde, East Renfrewshire and Renfrewshire

Internet address(es)

Main address

<http://riverclydehomes.org.uk>

Buyer's address

http://www.publiccontractsscotland.gov.uk/search/Search_AuthProfile.aspx?ID=AA12102

Section II: Object

II.1) Scope of the procurement

II.1.1) Title

Lift Maintenance Services

Reference number

RCH581

II.1.2) Main CPV code

- 50750000 - Lift-maintenance services

II.1.3) Type of contract

Services

II.1.4) Short description

River Clyde Homes wish to procure the services of an experienced and competent contractor to undertake Lift Maintenance for properties within Inverclyde.

Generally the works will include:-

- The comprehensive servicing and maintenance of circa 55 passenger lifts within High rise and Low rise buildings.
- The provision of an emergency call out and repair services.

More detailed information regarding the scope of the service required is provided in the specification document attached as Appendix F. The current Lift Estate is detailed within Appendix G.

Section VI. Complementary information

VI.6) Original notice reference

Notice number: [2023/S 000-030063](#)

Section VII. Changes

VII.1) Information to be changed or added

VII.1.2) Text to be corrected in the original notice

Section number

IV.2.2

Place of text to be modified

Time limit

Instead of

Date

29 November 2023

Local time

12:00pm

Read

Date

5 December 2023

Local time

12:00pm

VII.2) Other additional information

Outstanding question still not addressed by Technical Team.