

This is a published notice on the Find a Tender service: <https://www.find-tender.service.gov.uk/Notice/039246-2024>

Not applicable

## **Goods-Framework-Supply of LV Electric Motors**

United Utilities Water Limited

F14: Notice for changes or additional information

Notice identifier: 2024/S 000-039246

Procurement identifier (OCID): ocds-h6vhtk-04b3d1

Published 5 December 2024, 2:07pm

### **Section I: Contracting authority/entity**

#### **I.1) Name and addresses**

United Utilities Water Limited

Lingley Mere Business Park

Warrington

WA5 3LP

#### **Contact**

Ryan Seddon

#### **Email**

[ryan.seddon@uuplc.co.uk](mailto:ryan.seddon@uuplc.co.uk)

#### **Telephone**

+44 7771396216

#### **Country**

United Kingdom

**Region code**

UKD - North West (England)

**National registration number**

02366678

**Internet address(es)**

Main address

<https://www.unitedutilities.com>

Buyer's address

<https://uk.eu-supply.com/ctm/Company/CompanyInformation/Index/43984>

---

## Section II: Object

### II.1) Scope of the procurement

#### II.1.1) Title

Goods-Framework-Supply of LV Electric Motors

Reference number

PRO004555

#### II.1.2) Main CPV code

- 31110000 - Electric motors

#### II.1.3) Type of contract

Supplies

#### II.1.4) Short description

The requirement is for the supply of low voltage electric motors, predominantly on a replacement basis for motors linked to existing UU assets. UU has identified a requirement to improve the efficiency of the motors it purchases and therefore a drive to purchase motors certified to IE4 class efficiency where it is feasible to do so, and IE3 class efficiency where IE4 is not feasible. UU purchase a wide range of assets including, but not limited to, Pumps, Screens, Conveyors, Scrapers, Filtration Systems and Centrifuges. All of these assets are supplied with a motor, often unique to the performance of the asset, as a component of the equipment. If the motor fails at any point during the lifetime and cannot be repaired or it is deemed commercially unviable to repair, there is a need for UU to replace the motor in a timely manner to ensure production and site operations continue.

---

## Section VI. Complementary information

### VI.6) Original notice reference

Notice number: [2024/S 000-035691](#)

---

## Section VII. Changes

### VII.1.2) Text to be corrected in the original notice

Section number

IV.2.2

Instead of

Date

9 December 2024

Local time

3:00pm

Read

Date

16 December 2024

Local time

3:00pm