

This is a published notice on the Find a Tender service: <https://www.find-tender.service.gov.uk/Notice/011842-2023>

Contract

## **Kitchen canopy assessment and cleaning**

Belfast City Council

F03: Contract award notice

Notice identifier: 2023/S 000-011842

Procurement identifier (OCID): ocds-h6vhtk-0389e1

Published 25 April 2023, 2:19pm

### **Section I: Contracting authority**

#### **I.1) Name and addresses**

Belfast City Council

9 Adelaide Street

Belfast

BT2 8DJ

#### **Email**

[pmu@belfastcity.gov.uk](mailto:pmu@belfastcity.gov.uk)

#### **Telephone**

+44 2890320202

#### **Country**

United Kingdom

#### **Region code**

UKN06 - Belfast

**Internet address(es)**

Main address

<https://www.belfastcity.gov.uk/tenders>

**I.4) Type of the contracting authority**

Regional or local authority

**I.5) Main activity**

General public services

---

## **Section II: Object**

### **II.1) Scope of the procurement**

#### **II.1.1) Title**

Kitchen canopy assessment and cleaning

Reference number

ITT 36902

#### **II.1.2) Main CPV code**

- 90910000 - Cleaning services

#### **II.1.3) Type of contract**

Services

#### **II.1.4) Short description**

The scope of works shall consist of a risk assessment for the grease extraction systems and necessary cleaning required to eliminate, or, at the very least, minimize the risk of fire, and include the following:

The B&ES in TR19 Guidance to good food practice define kitchen extract ventilation as “the extract

systems intended to collect and remove contaminants, heat and moisture from cooking appliances”.

This includes all extract and supply or make-up ventilation that serves the following:

- Cooking ranges
- Fryers
- Ovens/microwave banks
- Pot wash/dish wash areas

Kitchen extract systems present particular hazards. As well as removing cooking odours and steam

from the kitchen areas, the extract system removes greasy vapours from cooking appliances which are

an ignition source.

The intention is to provide complete management and cleanliness of the kitchen extraction systems in

the premises with observations supported by photographs and, wet film thickness test measurements

taken to provide an objective account of each extract installation.

#### **II.1.6) Information about lots**

This contract is divided into lots: No

#### **II.1.7) Total value of the procurement (excluding VAT)**

Value excluding VAT: £43,545

### **II.2) Description**

#### **II.2.2) Additional CPV code(s)**

- 39714110 - Extraction ventilators
- 71315410 - Inspection of ventilation system

#### **II.2.3) Place of performance**

NUTS codes

- UKN06 - Belfast

#### **II.2.4) Description of the procurement**

The scope of works shall consist of a risk assessment for the grease extraction systems and necessary cleaning required to eliminate, or, at the very least, minimize the risk of fire, and include the following:

The B&ES in TR19 Guidance to good food practice define kitchen extract ventilation as “the extract

systems intended to collect and remove contaminants, heat and moisture from cooking appliances”.

This includes all extract and supply or make-up ventilation that serves the following:

- Cooking ranges
- Fryers
- Ovens/microwave banks
- Pot wash/dish wash areas

Kitchen extract systems present particular hazards. As well as removing cooking odours and steam

from the kitchen areas, the extract system removes greasy vapours from cooking appliances which are

an ignition source.

The intention is to provide complete management and cleanliness of the kitchen extraction systems in

the premises with observations supported by photographs and, wet film thickness test measurements

taken to provide an objective account of each extract installation.

#### **II.2.5) Award criteria**

Price

#### **II.2.11) Information about options**

Options: No

#### **II.2.13) Information about European Union Funds**

The procurement is related to a project and/or programme financed by European Union funds: No

---

## **Section IV. Procedure**

### **IV.1) Description**

#### **IV.1.1) Type of procedure**

Open procedure

#### **IV.1.8) Information about the Government Procurement Agreement (GPA)**

The procurement is covered by the Government Procurement Agreement: Yes

### **IV.2) Administrative information**

#### **IV.2.1) Previous publication concerning this procedure**

Notice number: [2022/S 000-034075](#)

---

## **Section V. Award of contract**

### **Title**

Kitchen canopy assessment and cleaning

A contract/lot is awarded: Yes

### **V.2) Award of contract**

#### **V.2.1) Date of conclusion of the contract**

18 April 2023

#### **V.2.2) Information about tenders**

Number of tenders received: 2

The contract has been awarded to a group of economic operators: No

#### **V.2.3) Name and address of the contractor**

Enviro Fire Water & Air Ltd

Milltown House, Milltown Industrial Estate, Warrenpoint

Newry

BT 34 3FN

Country

United Kingdom

NUTS code

- UKN08 - Newry, Mourne and Down

The contractor is an SME

Yes

#### **V.2.4) Information on value of contract/lot (excluding VAT)**

Total value of the contract/lot: £43,545

---

## **Section VI. Complementary information**

### **VI.4) Procedures for review**

#### **VI.4.1) Review body**

Belfast City Council

9 Adelaide Street

Belfast

BT2 8DJ

Country

United Kingdom