


## **Kingsway Moreton Avenue, Swanspool Brook Cycle/Foot Path**

Description of works:

The path is a current health and safety issue that needs attention, the path will need to be patched repaired.

Marked and numbered sections 1-23

Map of area start and finish point



Start point Charles Street NN8 2HZ

End Point Closest Location Northampton Road NN8 3GZ

### ***Site visit is mandatory***

#### **Specification of works.**

Set up compound and welfare facility for security of plant ( out of hours ), material storage area and welfare for staff.

Install safety barriers and signs.

Saw cut existing surface back to good tarmac.

Excavate and dispose of existing surface.

Weed kill area of excavation.

Install a tack coat emulsion and cold joint to sides.

Dispose of all arisings and area left clean

Areas Total of 794.88 sq metres.

Provide and lay 20mm base course macadam.

Provide and lay 6mm wearing course macadam.

Sizes of each patch (Sq)

1 : 19 x 0.6

2: 8.8 x 0.6

3: 21.5 x 0.6

4: 25 x 0.8

5: 11 x 0.6

6: 7.4 x 1.0

7: 5.8 x 1.0

8: 11.8 x 1.1

9: 7.8 x 1.3

10: 2.8 x 1.3

11: 6.9 x 0.6

12: 56 x 0.6

13: 164 x 0.8

14: 122 x 1.1

15: 65 x 0.9

16: 36 x 1.0 + 13 x 1.5 + 8 x 1 + 13 x 2.7

17: 56 x 0.8

18: 4 x 1.7 + 16 x 1

19: 10 x 0.9

20: 8 x 2.6

21: 9 x 0.9

22: 35 x 0.6

23: 43 x 2.6